



EQUIPMENT UPDATE

Effective Date:

Log Number: EU-1-371

Part: UNDER COUNTER PROTECTIVE LID

Models Affected: 180UC and GL-X

New Part Number: 14503.40

Old Part Number: 14503.50



BEFORE

Rocker switches are exposed and can be easily subjected to damage.



AFTER

The top lid has been extended to over hang and create a protective barrier for rocker switches.