




EQUIPMENT UPDATE

Effective Date: September 1, 2006

Log Number: EU-8-375

Part: CORNER DOOR SWITCH BRACKET

Models Affected: C



Field reports indicate the door safety switch has the potential of coming loose, causing machine malfunctions. CMA has received positive field response to the design change of securing the door safety switch on models AH and B.

The head of the screw prevents the switch from coming out of alignment or moving. Future machines will have this feature added.

Suggestions from CMA field Service Representatives are always welcomed and appreciated.