



CHANGE NOTICE

Effective Date: AUGUST 2008

Log Number: EU-08-403

Part Description: DOOR SWITCH BRACKET: 563.40 AND DOOR SWITCH ACTUATOR 563.42

Models Affected: AH / B / C / E / EST

This new positioning of the Door Switch places the actuator on the bottom of the switch, reducing the chances for moisture exposure; therefore, reducing service related issues. There are two parts involved: (1) the Door Switch Bracket and (2) Door Switch Actuator.



NOTICE !

NOTICE !

NOTICE !

NOTICE !

EFFECTIVE AUGUST 2008, CMA'S "CHANGE NOTICE'S" WILL BE E-MAILED

"FUTURE DISTRIBUTION WILL BE VIA E-MAIL ONLY."

PLEASE SEND YOUR E-MAIL ADDRESS AND CO. NAME TO:

joye.bradshaw@cmadishmachines.com

12700 KNOTT AVENUE
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com

