

EQUIPMENT UPDATE



Date: 2/9/04

Log Number: EU-02-361

Part: Drain Spring

Models Affected: VA & EVA

New Part Number: 00105.81

Old Part Number: N/A 00105.82

In order to improve the longevity of drain springs in dishmachine models VA & EVA, we have redesigned the end loops to eliminate stress points and wound the spring in counter clock wise direction to match the movement of the drain arm. This we believe will prevent premature failure of the drain spring. The new spring is green in color.



NOTE: long end loop must be connected to drain lever arm and short end loop connects to hole in frame of dishmachine.