

EQUIPMENT UPDATE



Effective Date: 9/1/05


Log Number: EU-09-367

Part: 1/3 HP OVERLOAD RELAY

Models Affected: CMA-44 & CMA-66 CONVEYOR

New Part Number: 13013.30

Old Part Number: N/A



CONVEYOR MOTOR OVERLOAD RELAY:

Underwriters Laboratory has requested that CMA supply overload protection on the CMA-44 and CMA-66 conveyor motor. As of September 1, 2005 all conveyor motor contactors have overload protection relays. If overload conditions were to occur, the relay will trip and can be field re-set.