



EQUIPMENT UPDATE

Effective Date: February 1, 2006


Log Number: EU-2-372

Part: MODEL C PAN SUPPORT

Models Affected: MODEL C

New Part Number: 01570.40

Old Part Number: 01570.14



BEFORE

Pan support rests on the underside of pan near the weld. Separation and impact damage sometimes occurs to the welded area during travel and movement by the freight carriers.



AFTER

To prevent transit damage to the welded area, CMA has changed the pan support design to fasten to the side of the pan. We have also repositioned the leg thus eliminating transit force movement to the welded area.