



# EQUIPMENT UPDATE

**Effective Date:** JANUARY 1, 2008

**Log Number:** EU-07-392

**Part Description:** Frese Valves:  
1/2" 41062.00  
3/4" 13029.00

**Model Affected:** MOST CMA DISHMACHINE MODELS



CMA has begun to install a new **Ball Strainer Valve** on almost all of our dishmachines. The new valve will prevent debris from entering the water valve which can cause malfunctions. The ball strainer valve serves as a major preventative component in protecting water valves from foreign matter. It will strain the water supplied to the dishmachine and purify the flow. The ball strainer screen will need to be occasionally removed and cleaned for optimal results.



12700 KNOTT AVENUE  
GARDEN GROVE, CALIF. 92841  
800-854-6417 • 714-898-8781  
FAX 714-895-2141  
[www.cmadishmachines.com](http://www.cmadishmachines.com)

