


SERVICE BULLETIN

Date: MARCH 10, 2008
Log Number: 113
Model Affected: GL-X
Subject: TIMER SPLASH SHIELD PN# 00408.71



The GL-X has been retrofitted with a *"Timer Splash Shield"* to minimize moisture contact with the mechanical cam timer. Installing *"Timer Splash Shield"* gives additional assurance that the electronics **"will not"** be subjected to moisture, and will prevent service related issues.

The GL-X *"Timer Splash Shield"* PN#00000.00 can be ordered for field retrofit. The shield will be provided with a double back tape for easy installation.

It is recommended you order and put into place this preventive protection shield. CMA recommends installing this shield on all GL-X Glasswashers in the field. CMA will supply at no charge if ordered with-in the next 60 days.

