



# CHANGE NOTICE

**Effective Date:** AUGUST 2008

**Log Number:** EU-08-403

**Part Description:** DOOR SWITCH BRACKET: 563.40 AND DOOR SWITCH ACTUATOR 563.42

**Models Affected:** AH/B/C/E/EST

This new positioning of the Door Switch places the actuator on the bottom of the switch, reducing the chances for moisture exposure; therefore, reducing service related issues. There are two parts involved: (1) the Door Switch Bracket and (2) Door Switch Actuator.



**NOTICE ! NOTICE ! NOTICE ! NOTICE !**

EFFECTIVE AUGUST 2008, CMA'S "CHANGE NOTICE'S" WILL BE E-MAILED

**"FUTURE DISTRIBUTION WILL BE VIA E-MAIL ONLY."**

PLEASE SEND YOUR E-MAIL ADDRESS AND CO. NAME TO:

**[joye.bradshaw@cmadishmachines.com](mailto:joye.bradshaw@cmadishmachines.com)**

12700 KNOTT AVENUE  
GARDEN GROVE, CALIF. 92841  
800-854-6417 • 714-898-8781  
FAX 714-895-2141  
[www.cmadishmachines.com](http://www.cmadishmachines.com)

