

EQUIPMENT UPDATE



Date: 2/2/04

Log Number: EU-02-360

Part: Final Rinse Switch Assembly

Models Affected: CMA-44/CMA-66

New Part Number: 13408.61

Old Part Number: N/A 13408.85

CMA is introducing a newly improved Final Trip Switch Assembly on the CMA-44/66 conveyors. This new rinse switch uses a magnetic reed switch, externally mounted away from moisture. We believe this will prove to be a more reliable design application.

