



# EQUIPMENT UPDATE

**Effective Date:** SEPTEMBER 1, 2006


**Log Number:** EU-9-378

**Part:** CONVEYOR CLUTCH SPRING


**Models Affected:** CMA-44/CMA-66 CONVEYORS

**New Part Number:** 13508.70

**Old Part Number:** 13508.60



Present Conveyor Clutch Spring has a tendency to break under heavy load and use.



The NEW Conveyor Clutch Spring has been strengthened and improved to prevent premature breakage. The coil gauge and tensile is considerably stronger.