



# EQUIPMENT UPDATE

**Effective Date:** SEPTEMBER 1, 2006

**Log Number:** EU-9-377

**Part:** TIMERS


**Models Affected:** CMA-44/CMA-66/CMA-180

**New Part Number:** 13418.20

**Old Part Numbers:** 13418.85 / 13419.85



Timer has variable settings that are not needed for our application. This has created confusion when setting the time sequence.



New timer has single setting feature. Simply adjust the time sequence up or down to your application.