



# EQUIPMENT UPDATE

**Effective Date:** SEPTEMBER 1, 2006

**Log Number:** EU-9-379

**Part Description:** CB DOOR HANDLE LINK

**Models Affected:** CORNER B

**New Part Number:** 1553.30

**Old Part Number:** 1553.10



The new Corner B door handle link provides additional space between tables and door link.

