




EQUIPMENT UPDATE

Effective Date: APRIL 1, 2008

Log Number: EU-08-398

Part Description: CHEMICAL SUPPORT BRACKETS (TALL PN# 1558.20 SHORT PN# 1558.30)

Models Affected: ALL STRAIGHT THRU MODELS



Liquid sanitizer (chlorine) can be damaging to dishmachines if the product is not dispensed properly. CMA has developed two versions of a “**Chemical Support Bracket**”, one for standard CMA door machines (straight thru models) and another shorter version that will fit most of our older models. The **Chemical Support Bracket** has a chemical trough directly below the dispensing lines. The trough is below the water line and is rinsed every cycle. This will aid in the prevention of corrosion, thereby helping to preserve the dishmachine sump area. CMA highly recommends that the **Chemical Support Bracket** be added to all straight thru model dishmachines to prevent chemical damage and preserve your dishmachine.



12700 KNOTT AVENUE
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com

