

# SERVICE BULLETIN

**Date:** FEBRUARY 7, 2011  
**Log Number:** 122  
**Models Affected:** ALL DISHMACHINE MODELS  
**Subject:** POWER CORD/GFI OUTLET

---



## **POWER CORD/ GFI OUTLET**

Warning: UL921 Standard requires all dishmachines **not considered portable** (including undercounters) be **hardwired only**. CMA continues to receive service calls from its customers relating to undersized power cords, and old worn out receptacles which contribute to circuit breakers tripping. We have also heard of machines that are being plugged into GFI circuits, which cannot handle the in-rush load of a wash pump motor at start up and will trip. These are all non-electric code approved installations and could become a liability issue for your company.



12700 KNOTT STREET  
GARDEN GROVE, CALIF. 92841  
800-854-6417 • 714-898-8781  
FAX 714-895-2141  
[www.cmadishmachines.com](http://www.cmadishmachines.com)