



CMA PRODUCT IMPROVEMENT

Effective Date: JUNE 2016
Log Number: CMA-PI-470
Subject: SPLASH SHIELD
Models Affected: L-1X, L-1X16, GL-X

Splash Shield

CMA has added a Mylar splash shield on our L-1X, L1X16 and GL-X dishmachines to protect the peristaltic pump motors and prime switches from excess water (usually caused by operator error) flowing directly onto the switches and motors. The excess water could cause an electrical dead short.

The Mylar material is chemical, heat, split resistant.



12700 KNOTT STREET
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com