

SERVICE BULLETIN



Effective Date: JANUARY 1, 2013
Log Number: 126
Subject: 180UC PUMP INTAKE SECONDARY SPOON SCREEN PN 14562.00
List Price: \$61.20
Model Affected: CMA-180UC

180UC PUMP INTAKE SECONDARY SPOON SCREEN

As a special request, CMA was asked to provide a secondary filter to the pump system, in the event the end user has difficult pre-scraping conditions. The “Pump Intake Secondary Spoon Screen” snaps over the machine’s existing “pump screen”, and filters out smaller debris from entering the wash pump and wash arms.

The “Pump Intake Secondary Spoon Screen” is built with smaller holes and should be monitored daily, cleaning as necessary. To help avoid service calls, CMA recommends that this screen be used on machines exposed to poor pre-scraping conditions.

List Price: \$61.20



12700 KNOTT STREET
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com