

EQUIPMENT UPDATE



Date: 2/2/04

Log Number: EU-02-358

Part: 13504.12 Gear Reduce Left
13504.00 Gear Reduce Right

Models Affected: CMA-44 CMA-66

New Part Number:

Old Part Number: N/A

CMA now provides a Sight Glass on all gear boxes to monitor the oil level. If servicing the gear box and need to separate the motor from the gear box, remove 4 bolts connecting motor to gear box. Using the same bolts, thread bolts into separation flange holes simultaneously until motor separates from gear box.

