




# EQUIPMENT UPDATE

**Effective Date:** OCTOBER 1, 2006

**Log Number:** EU-9-380

**Part Description:** THERMOMETER RELOCATION

**Models Affected:** CMA-180 / CMA-44 / CMA-66



To help make the thermometers easier to service they have been relocated to the outer edge of the control panel. This will allow entering from the back (inside) to adjust or remove easily.